

Bulletin 2023.3 Update on Filter Monitor Emergency Actions December 2023



On October 4, 2023, Facet Filtration notified the industry that an internal quality test detected Super Absorbent Polymer (SAP) downstream of their filter monitor elements. Airlines for America subsequently released [A4A Bulletin 2023.2](#) which included eight mandatory emergency mitigating actions. Action 1 required removal of all Facet-brand filter monitor elements no later than January 1, 2024. However, due to supply chain challenges and a need to ensure adequate replacement product production quality, the original deadline will not be met. Therefore, Action 1 of Bulletin 2023.2 is modified as follows: Facet filter monitors shall be removed from service **no later than April 1, 2024**. All other actions/requirements in Bulletin 2023.2 remain unchanged.

Questions or requests for further information should be submitted to fuel@airlines.org
###